



It's shipping & survey

CISS GROUP PTE.LTD.

Registry address: 10 Anson Road , # 20-05,

International Plaza, Singapore, 079903

Reg.No 201618838R

Operation office: 77 Science Park Drive Str.,

CINTECH III Business Center, #03-25/26,

Singapore 118256

DAILY SURVEY REPORT

Vessel/
Installation : XXXX

Location : Bali Ampar, Indonesia

Customer : XXXX

Date : XX/XX/2023

Job number : SGD00XXX

Client Ref No : XXXXX


List of jobs done/performed by today:

- Hatch covers Ultrasonic water tightness tests;





There are total 4 holds in the vessel.

Ship visit XX.XX.2023

PHOTO REPORT






General view and testing of the Ultrasonic transmitters before inspection



HOLD No1, USWT test

There is one problematic zone found on the vessel's port side, hold No1 with a reading of more, than 10%.





It's shipping & survey

CISS GROUP PTE.LTD.

Registry address: 10 Anson Road , # 20-05,





International Plaza, Singapore, 079903

Reg.No 201618838R

Operation office: 77 Science Park Drive Str.,

CINTECH III Business Center, #03-25/26,

Singapore 118256



HOLD No2, USWT measurements




It's shipping & survey

CISS GROUP PTE.LTD.

Registry address: 10 Anson Road , # 20-05,
International Plaza, Singapore, 079903




Reg.No 201618838R

Operation office: 77 Science Park Drive Str.,
CINTECH III Business Center, #03-25/26,
Singapore 118256



HOLD 3, USWT test

HOLD No4 USWT test






It's shipping & survey

CISS GROUP PTE.LTD.

Registry address: 10 Anson Road , # 20-05,
International Plaza, Singapore, 079903
Reg.No 201618838R

Operation office: 77 Science Park Drive Str.,
CINTECH III Business Center, #03-25/26,
Singapore 118256



HOLD No4 USWT test

The HCs test passed.
THE END OF REPORT

Dated: XX of XXXX, 2023

