



Commodities International
Shipping and Survey



FOSFA
INTERNATIONAL

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: SGD01237

ORIGINAL

UNSEALING CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN CRUDE SUNFLOWER OIL IN BULK
Vessel: M/T ELIANA
Quantity: 5250,000 MT
B/L No. & Date: NO.1 DD 26.01.2024
Shipper: SUNOLTA OU
HARJU MAAKOND, TALLINN,
KESKLINNA LINNAOSA,
JOE TN 4C, 10151 ESTONIA
Consignee: TAMPIERI SPA – VIA GRANAROLO N. 177/3 – 48018
FAENZA RAVENNA – ITALY
Notify address: TAMPIERI SPA – VIA GRANAROLO N. 177/3 – 48018
FAENZA RAVENNA – ITALY
Port of loading: ODESA, UKRAINE
Port of discharge: RAVENNA, ITALY
Vessel Tanks Nos.: 1P,2P,3P,4P,5P,1S,2S,3S,4S,5S

This is to certify that the undersigned CISS Group, unsealed the cargo tanks of the M/T ELIANA prior commenced of unloading operations. All tanks and valves have been unsealed as follows:

Port		Starboard	
Position	Seals No:	Position	Seals No:
1P	D57429981, D57429982, D57429983	1S	D57429996, D57429997, D57429998
2P	D57429984, D57429985, D57429986, D57429290	2S	D57429999, D57430000, D57429491, D57429492
3P	D57429987, D57429988, D57429989	3S	D57429493, D57429494, D57429495
4P	D57429990, D57429991, D57429992	4S	D57429496, D57429497, D57429498
5P	D57429993, D57429994, D57429995	5S	D57429499, D57429500, D57429260
Manifolds	C82137166	Manifolds	C82137167

This certificate is electronically signed and stamped.

DATED: 09 of FEBRUARY 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA



This certificate is issued to any job or services carried out within the GENERAL TERMS AND CONDITION OF BUSINESS printed overleaf. This certificate is not intended to relieve the parties of any relevant sales contract from their contractual obligations. The Company's responsibility under this Certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees.