



**Commodities International
Shipping and Survey**



**FOSFA
INTERNATIONAL**

CISS GROUP UKRAINE LLC
member of **CISS GROUP Pte.Ltd. (Singapore)**
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

Page 1/2

CERTIFICATE No.: SGD01246

ORIGINAL

UNSEALING CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	BL NO. 1 STANDARD CRUDE SUNFLOWERSEED OIL, IN BULK BL NO. 2 UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL IN BULK
Vessel:	M/T SEAVEN VOYAGER
Quantity:	BL NO. 1 – 3850,000 MT BL NO. 2 – 2200,000 MT
B/L No. & Date:	NOS. 1 AND 2 DD 02.02.2024
Shipper:	SUNOLTA (SUISSE) SA RUE DU 23-JUIN 26, 2800 DELEMONT, SWITZERLAND
Consignee:	TO ORDER
Notify address:	BL NO. 1 F.FAIGES S.L. COMERCIO 51 43500 TORTOSA (TARRAGONA) / SPAIN BL NO. 2 BERNARDGROUP SP. Z O.O. STR. GESIA 8/205, 31-535 KRAKOW, POLAND
Port of loading:	ODESA, UKRAINE
Port of discharge:	SEVILLE, SPAIN
Vessel Tanks Nos.:	1P,4P,5P,6P,SP,1S,4S,5S,6S,SS 2P,3P,2S,3S

This is to certify that the undersigned CISS Group, unsealed the cargo tanks of the M/T SEAVEN VOYAGER prior commenced of unloading operations. All tanks and valves have been unsealed as follows:





**Commodities International
Shipping and Survey**



**FOSFA
INTERNATIONAL**

CISS GROUP UKRAINE LLC
member of **CISS GROUP Pte.Ltd. (Singapore)**
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

Page 2/2

CERTIFICATE No.: SGD01246

ORIGINAL

Port			Starboard		
Position		Seals No:	Position		Seals No:
1P	Hatch cover	D57430337	1S	Hatch cover	D57430301
	Hatch cover	D57430338		Hatch cover	D57430302
	Hatch cover	D57430316		Hatch cover	D57430323
2P	Hatch cover	D57430339	2S	Hatch cover	D57430303
	Hatch cover	D57430340		Hatch cover	D57430304
	Hatch cover	D57430317		Hatch cover	D57430324
3P	Hatch cover	D57430341	3S	Hatch cover	D57430305
	Hatch cover	D57430342		Hatch cover	D57430306
	Hatch cover	D57430318		Hatch cover	D57430325
4P	Hatch cover	D57430343	4S	Hatch cover	D57430307
	Hatch cover	D57430344		Hatch cover	D57430308
	Hatch cover	D57430319		Hatch cover	D57430326
5P	Hatch cover	D57430345	5S	Hatch cover	D57430309
	Hatch cover	D57430346		Hatch cover	D57430310
	Hatch cover	D57430320		Hatch cover	D57430327
6P	Hatch cover	D57430347	6S	Hatch cover	D57430311
	Hatch cover	D57430348		Hatch cover	D57430312
	Hatch cover	D57430321		Hatch cover	D57430328
SLOP P	Hatch cover	D57430349	SLOP S	Hatch cover	D57430313
	Hatch cover	D57430350		Hatch cover	D57430314
	Hatch cover	D57430322		Hatch cover	D57430329
1P	MANIFOLDS	D57429454	1S	MANIFOLDS	D57429485
2P	MANIFOLDS	D57429453	2S	MANIFOLDS	D57429484
3P	MANIFOLDS	D57429451	3S	MANIFOLDS	D57429483
4P	MANIFOLDS	D57429452	4S	MANIFOLDS	D57430336
5P	MANIFOLDS	D57429455	5S	MANIFOLDS	D57430331
6P	MANIFOLDS	D57429446	6S	MANIFOLDS	D57430332
SLOP P	MANIFOLDS	D57429450	SLOP S	MANIFOLDS	D57430333
1 P/S; 4P/S; 5 P/S; 6 P/S; SLOP P/S CROSOVER		C82137192	2 P/S; 3 P/S CROSOVER		C82137191

This certificate is electronically signed and stamped.

DATED: 19 of FEBRUARY 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA



This certificate is issued to any job or services carried out within the GENERAL TERMS AND CONDITION OF BUSINESS printed overleaf. This certificate is not intended to relieve the parties of any relevant sales contract from their contractual obligations. The Company's responsibility under this Certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees.