

Commodities International Shipping and Survey

CISS Group PTE. LTD. 10, Anson Road, #29-05 A, International Plaza, Singapore, 079903. e-mail: inspection@ciss-group.com

CERTIFICATE No.: UA01017

ORIGINAL

CERTIFICATE STATING LAST 3 CARGOES

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

CRUDE SUNFLOWER OIL

Vessel: Quantity: MT AQASIA 1990,740 MT

B/L No. & Date:

NO. 14 DD. 06.09.2020

Shipper:

LLC BELAZ

65490, UKRAINE, TEPLODAR, AV. ENERGETYKIV, 73. OF. 1

Consignee:

TO ORDER

Notify address:

Port of loading:

AFIA INTERNATIONAL EGYPT COMPANY - SAVOLA

EGYPT - 9, ELMASANEA ST. INDUSTRIAL ZONE. DISTRICT # 6- NASR CITY - CAIRO - EGYPT

IZMAIL, UKRAINE

Port of discharge:

DAMIETTA PORT, EGYPT

Vessel Tanks Nos.:

1P, 1S, 2P, 2S, 5P, 5S, 6P AND 6S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

	Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
CARALI DINCON	1P, 1S, 2P, 2S, 5P, 5S, 6P, 6S	HYDRAULIC 32	SN 500	METHYL ALCOHOL
	01,00,01,00	A CANADA	ISS DISS CISS DISS DISS CISS CAS CAS CAS CAS CAS CAS CAS CAS CAS C	THE COST COST COST COST COST COST COST COST

These findings are valid for the time and place of inspection only. The certificate does not relieve the

Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 06 OF SEPTEMBER, 2020 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA







