



**Commodities International
Shipping and Survey**



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: UA01017

ORIGINAL

TANKS CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWER OIL
Vessel:	MT AQASIA
Quantity:	1990,740 MT
B/L No. & Date:	NO. 14 DD. 06.09.2020
Shipper:	LLC BELAZ 65490, UKRAINE, TEPLDAR, AV. ENERGETYKIV, 73. OF. 1
Consignee:	TO ORDER
Notify address:	AFIA INTERNATIONAL EGYPT COMPANY – SAVOLA EGYPT – 9, ELMASANEA ST. INDUSTRIAL ZONE, DISTRICT # 6- NASR CITY – CAIRO – EGYPT
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	DAMIETTA PORT, EGYPT
Vessel Tanks Nos.:	1P, 1S, 2P, 2S, 5P, 5S, 6P AND 6S

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P, 1S, 2P, 2S, 5P, 5S, 6P, 6S	HYDRAULIC 32	SN 500	METHYL ALCOHOL

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 06 OF SEPTEMBER, 2020

**For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA**

