



**Commodities International
Shipping and Survey**



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: UA01045

ORIGINAL

HOLDS CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

Vessel:

Quantity:

BL No. & Date:

Shipper:

SUNFLOWER EXTRACTION MEAL IN PELLETS, IN BULK

M/V «RHINE RIVER»

6001,840 MT

NO. 1 AND 2 DD 24.11.2020

"GRAIN TRADING HOUSE " LLC

Ukraine, Kyiv, str. Vasylykivska, 2-A

ON BEHALF OF CEREALES Y HARINAS GARSAN SPAIN

LLC MARLENE TREND

04050, Ukraine,

Kiev, st. Glybochitska, 17, bldg. 8, letter 1-D, of. 323.4

ON BEHALF OF CEREALES Y HARINAS GARSAN SPAIN

TO ORDER

Consignee:

Notify Address:

BORSARI E.&C. SRL,

VIA DI MEZZO 114/E

41015 NONANTOLA (MO)

ITALY

Port of loading:

Port of discharge:

IZMAIL, UKRAINE

RAVENNA, ITALY

As a result of our visual examinations, visibly accessible parts of vessel's holds Nos. 1, 2 and 3 were inspected and found to be dry and clean, swept and suitable to carry:

SUNFLOWER EXTRACTION MEAL IN PELLETS, IN BULK

Last cargoes as declared by the vessel:

- DRY DOCK;
- DRY DOCK;
- DRY DOCK;

Holds Inspected 20 of NOVEMBER 2020 from 21:30 hrs. to 22:00 hrs.

The results of inspection are valid for the time and place of inspection only.

DATED: 24 of NOVEMBER, 2020

For and on behalf of CISS GROUP Ukraine LLC

Registered Superintendent and Surveyor Member of GAFTA

