



1/1

CISS Group PTE. LTD. 10, Anson Road, #29-05 A, International Plaza, Singapore, 079903. e-mail: inspection@ciss-group.com

**CERTIFICATE No.: UA00991** 

**ORIGINAL** 

## **CERTIFICATE STATING LAST 3 CARGOES ARE CLEAN & UNLEADED**

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

UKRAINIAN CRUDE SUNFLOWERSEED OIL, IN BULK

Vessel:

MT SEAVEN VOYAGER

Quantity:

Shipper:

3000,260 MT

B/L No. & Date:

Nos. 1, 2, 3 AND 4 DD. 14.06.2020

LLC "CAREFIELD"

21037, VINNYTSIA, AKADEMIKA JUSHCHENKA STREET, 10,

PREMICES 13N, POD NUMEREM 43296758

«Kublich Grain» LLC

23818, st. Railway, 12, Kublich village, Teplitsky district, Vinnitsa

region

LLC «Company Prometey»

54030, Ukraine, Nikolaev, Pushkinskaya str., 8

"ODESKA TORGOVA KOMPANIA" LLC

Ukraine, Odessa region, Odessa, Church str.,19

TO ORDER

Notify address:

Bunge Italia SPA,

Via Baiona, 203 Ravenna, Italy

Port of loading:

Consignee:

IZMAIL, UKRAINE

Port of discharge:

Ravenna Port, Italy

Vessel Tanks Nos.:

1P, 1S, 5P, 5S, 6P, 6S, SP AND SS

## RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

	Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
5)	1P,1S,5P,5S	SUNFLOWER OIL	SUNFLOWER OIL	SUNFLOWER OIL
	6P,6S,SP,SS	SUNFLOWER OIL	SUNFLOWER OIL	SUNFLOWER OIL

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

> **DATED: 14 OF JUNE. 2020** For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA





