



**Commodities International
Shipping and Survey**



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: UA00991

ORIGINAL

TANKS CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN CRUDE SUNFLOWERSEED OIL, IN BULK
Vessel:	MT SEAVEN VOYAGER
Quantity:	3000,260 MT
B/L No. & Date:	Nos. 1, 2, 3 AND 4 DD. 14.06.2020
Shipper:	LLC "CAREFIELD" 21037, VINNYTSIA, AKADEMIKA JUSHCHENKA STREET, 10, PREMICES 13N, POD NUMEREM 43296758 «Kublich Grain» LLC 23818, st. Railway, 12, Kublich village, Teplitsky district, Vinnitsa region LLC «Company Prometey» 54030, Ukraine, Nikolaev, Pushkinskaya str., 8 "ODESKA TORGOVA KOMPANIA" LLC Ukraine, Odessa region, Odessa, Church str., 19
Consignee:	TO ORDER
Notify address:	Bunge Italia SPA, Via Baiona, 203 Ravenna, Italy
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	Ravenna Port, Italy
Vessel Tanks Nos.:	1P, 1S, 5P, 5S, 6P, 6S, SP AND SS

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P,1S,5P,5S	SUNFLOWER OIL	SUNFLOWER OIL	SUNFLOWER OIL
6P,6S,SP,SS	SUNFLOWER OIL	SUNFLOWER OIL	SUNFLOWER OIL

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 14 OF JUNE, 2020

**For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA**

