



CISS Group PTE. LTD.
10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciiss-group.com

CERTIFICATE No.: UA01211/1

ORIGINAL

TANK INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: CRUDE SUNFLOWER OIL IN BULK. TARIC CODE 15121110
Vessel: BRP - TE-2
Quantity: 1000,680 MT
B/L No. & Date: NO. 1 DD 07.02.2022
Shipper: "ODESKA TORGOVA KOMPANIA" LLC
Ukraine, Odessa region,
Odessa, Church str.,19
ON BEHALF OF BSS GROUP LTD
Consignee: Astra Bioplant LTD,
23 Bulgaria str, 7060 Slivo Pole, Bulgaria
VAT: BG117650594
Notify address: Astra Bioplant LTD,
23 Bulgaria str, 7060 Slivo Pole, Bulgaria
VAT: BG117650594
Port of loading: IZMAIL, UKRAINE
Port of discharge: RUSE, BULGARIA
Vessel Tanks Nos.: 1, 2, 3, 4, 5, 6, 7 AND 8

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Table with 4 columns: Ships Tanks N°, Last cargo, Second Last Cargo, Third Last Cargo. Rows 1-8 showing inspection results for various tanks.

These findings are valid for the time and place of inspection only.
The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 7th OF FEBRUARY, 2022
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

