





Page 1/2

CISS Group PTE. LTD.

Vessel:

Port of loading:

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903. e-mail: inspection@ciss-group.com

CERTIFICATE No.: UA01229/3

ORIGINAL

HOLDS SEALING CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN SUNFLOWER MEAL IN PELLETS CROP

2021 IN BULK M/V Laurus 1000,000 MT

Quantity: 1000,000 MT BL No. & Date: NO. 3 DD 07.04.2022

Shipper: "ODESKA TORGOVA KOMPANIA" LLC

Ukraine, Odessa region, Odessa, Church str.,19

ON BEHALF OF BSS GROUP LTD

Consignee: TO ORDER

Notify Address: Hany For Trade for import and agencies

Almaraw Building, Elmesaha St., Shibin El Kom,

Monofia , Egypt IZMAIL. UKRAINE

Port of discharge: ANY EGYPTIAN MEDITERRANEAN PORT

ACID no : 4937136542022030119

Egyptian Importer Tax ID: 493-713-654 FOREIGN EXPORTER NAME: "BSS GROUF

FOREIGN EXPORTER NAME: "BSS GROUP" LTD
Registration Type: Company Registration Number

Foreign Exporter ID: 206729988
Foreign Exporter Country: BULGARIA

Foreign Exporter Country Code: BG

We, CISS GROUP Ukraine LLC, hereby certify that we performed sealing of the cargo Holds Nos. 1 and 2 and manholes of M/V Laurus, upon completion of loading. All holds and hatches have been closed and sealed. Date: 07.04.2022 sealing from: 17:30 hrs to: 18:30 hrs

	Seal No Color Color (195 Color		
Hold No	Hatches Hatches		noles s ciss ciss ciss ciss
AS CISS CISS CAS CIS	SCISS CISS CISS CISS CISS CISS CAS CI	SCISS CISS Fores CISS CISS	As ciss ciss Aft Cos ciss ciss
VS CISS CISS CISS CISS CISS CISS	S CISS CISS C53581551 CISS CISS CISS CISS CISS CISS CISS CIS	IS CISS CISS CISS CISS CISS	C42264538
AS CISS CIS 2GISS CASS CIS	C53581552	C42264539	108 CISS CISS CISS CISS CISS

The results of inspection are valid for the time and place of inspection only.

DATED: 7th of APRIL, 2022
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of GAFTA



