



Commodities International
Shipping and Survey



FOSFA
INTERNATIONAL

CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: UA01296

ORIGINAL

ORIGINAL TANK INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL IN BULK
Vessel: MT VEYSEL VARDAL
Quantity: 3004,080 MT
B/L No. & Date: NO. 1 DD 19.07.2022
Shipper: LIMITED LIABILITY COMPANY "RINHOLD SKIL"
03189, Ukraine, Kyiv, street Academician Williamsa, bldg. 8-E
Consignee: TO ORDER
Notify address: BERNARDGROUP SP. Z O.O,
UL. GEN. LEOPOLDA OKULICKIEGO,
NR 14, LOK 27, RZESZÓW, POLAND
Port of loading: IZMAIL, UKRAINE
Port of discharge: SEVILLE, SPAIN
Vessel Tanks Nos.: 1C,2C,3C,4C AND 5C

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1C	CRUDE SUNFLOWER OIL 90%	CRUDE SUNFLOWER OIL 90%	CRUDE PALM OIL 95%
2C	CRUDE SUNFLOWER OIL 94%	CRUDE SUNFLOWER OIL 94%	CRUDE PALM OIL 93,2%
3C	CRUDE SUNFLOWER OIL 95%	CRUDE SUNFLOWER OIL 95%	CRUDE PALM OIL 95%
4C	CRUDE SUNFLOWER OIL 95%	CRUDE SUNFLOWER OIL 95%	CRUDE PALM OIL 95%
5C	CRUDE SUNFLOWER OIL 95%	CRUDE SUNFLOWER OIL 95%	CRUDE PALM OIL 95%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 19th of JULY, 2022

For and on behalf of CISS GROUP Ukraine LLC

Registered Superintendent and Surveyor Member of FOSFA

