



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: UA01352

ORIGINAL

LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL IN BULK
Vessel: M/T "EFE"
Quantity: 7250,000 MT
B/L No. & Date: NO. 1 AND 2 DD 16.08.2022
Shipper: GNT TRADE DMCC
OFFICE 32A, GOLD TOWER,
CLUSTER1, JLT, DUBAI, UAE
Consignee: TO ORDER
Notify address: PIER AGRO GIDA SAN. VE TIC.A.S.
ADANA YUMURTALIK SERBEST BOLGE SB.
SARIMAZI SERBEST BOLGE MAH.
ADANA YUMURTALIK SERBEST BOLGESI
CEYHAN – ADANA
Port of loading: ODESSA, UKRAINE
Port of discharge: TOROS PORT, CEYHAN/TURKEY
Vessel Tanks Nos.: 1C, 2P, 2S, 3P, 3S, 4P, 4S, 5P, 5S, 6P, 6S, 7P, 7S, 8P AND 8S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1C	ULSD 98%	ULSD 95%	ULSD 98%
2P	VEGOIL 86%	ULSD 97%	ULSD 95%
2S	VEGOIL 85%	ULSD 97%	ULSD 95%
3P	VEGOIL 85%	ULSD 97%	ULSD 95%
3S	VEGOIL 80%	ULSD 97%	ULSD 95%
4P	VEGOIL 86%	ULSD 97%	GASOLINE 94%
4S	VEGOIL 80%	ULSD 97%	GASOLINE 94%
5P	VEGOIL 92%	ULSD 97%	ULSD 95%
5S	VEGOIL 85%	ULSD 97%	ULSD 95%
6P	VEGOIL 90%	ULSD 97%	ULSD 95%
6S	VEGOIL 85%	ULSD 97%	ULSD 95%
7P	VEGOIL 87%	ULSD 97%	ULSD 95%
7S	VEGOIL 80%	ULSD 95%	ULSD 95%
8P	ULSD 70%	ULSD 95%	ULSD 95%
8S	ULSD 70%	ULSD 95%	ULSD 95%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 16th of AUGUST, 2022

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

