

CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

**CERTIFICATE No.: UA01371/1**

**ORIGINAL**

## **ORIGINAL TANK INSPECTION CERTIFICATE**

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL, IN BULK
Vessel:	MT MRC SEMIRAMIS
Quantity:	1061,600 MT
B/L No. & Date:	NO. 1 DD 14.09.2022
Shipper:	"ODESKA TORGOVA KOMPANIA" LLC Ukraine, Odessa region, Odessa, Church str.,19 ON BEHALF OF BSS GROUP LTD
Consignee:	TO ORDER
Notify address:	SAYINLAR GIDA MADDELERI SANAYI VE TICARET A.S. 3.Organize Sanayi Bölgesi 83303 nolu Cadde No:3 Sehitkamil – GAZIANTEP, TURKIYE
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	DORTYOL, TÜRKIYE
Vessel Tanks Nos.:	1S,2S,3S,4S,5S,6S,1P,2P,3P,4P,5P,6P

### **RESULTS OF INSPECTION**

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	GASOIL	VEGOIL	GASOIL
1S	GASOIL	VEGOIL	GASOIL
2P	GASOIL	VEGOIL	GASOIL
2S	GASOIL	VEGOIL	GASOIL
3P	GASOIL	VEGOIL	GASOIL
3S	GASOIL	VEGOIL	GASOIL
4P	GASOIL	VEGOIL	GASOIL
4S	GASOIL	VEGOIL	GASOIL
5P	GASOIL	VEGOIL	GASOIL
5S	GASOIL	VEGOIL	GASOIL
6P	GASOIL	VEGOIL	GASOIL
6S	GASOIL	VEGOIL	GASOIL

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

**This certificate is electronically signed and stamped.**

**DATED: 14 of SEPTEMBER, 2022**

**For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA**

