

CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

CERTIFICATE No.: UA01371/2

ORIGINAL

LAST THREE CARGOES

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

Vessel:

Quantity:

B/L No. & Date:

Shipper:

UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL, IN BULK
MT MRC SEMIRAMIS

4621,280 MT

NO. 2 DD 14.09.2022

LIMITED LIABILITY COMPANY "RINHOLD SKIL"

03189, Ukraine, Kyiv, street Academician Williamsa, bldg. 8-E

ON BEHALF OF AGRO TRADE GLOBAL FZC

Consignee:

Notify address:

TO ORDER

SAYINLAR GIDA MADDELERI SANAYI VE TICARET A.S.

3.Organize Sanayi Bölgesi 83303 nolu Cadde No:3

Sehitkamil – GAZIANTEP, TURKIYE

Port of loading:

Port of discharge:

Vessel Tanks Nos.:

IZMAIL, UKRAINE

DORTYOL, TÜRKIYE

1S,2S,3S,4S,5S,6S,1P,2P,3P,4P,5P,6P

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	GASOIL	VEGOIL	GASOIL
1S	GASOIL	VEGOIL	GASOIL
2P	GASOIL	VEGOIL	GASOIL
2S	GASOIL	VEGOIL	GASOIL
3P	GASOIL	VEGOIL	GASOIL
3S	GASOIL	VEGOIL	GASOIL
4P	GASOIL	VEGOIL	GASOIL
4S	GASOIL	VEGOIL	GASOIL
5P	GASOIL	VEGOIL	GASOIL
5S	GASOIL	VEGOIL	GASOIL
6P	GASOIL	VEGOIL	GASOIL
6S	GASOIL	VEGOIL	GASOIL

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 14 of SEPTEMBER, 2022

For and on behalf of CISS GROUP Ukraine LLC

Registered Superintendent and Surveyor Member of FOSFA

