





Page

1/2

CISS Group PTE. LTD.

Notify address:

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903. e-mail: inspection@ciss-group.com

CERTIFICATE No.: UA01385

ORIGINAL

TANK CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: Crude Sunflower Oil in bulk. Taric Code 15121110

Vessel: ELAN Quantity: 959,380 MT

B/L No. & Date: NO. 1 DD 30.09.2022

Shipper: "IZMAILSKA TORGOVA COMPANIA" LLC

Address: Ukraine, Odessa region,

Izmail, st. Osipenka, 30

ON BEHALF OF D.A.M TRADE GROUP LLC

Consignee: Astra Bioplant LTD,

23 Bulgaria str, 7060 Slivo Pole,

Bulgaria

VAT: BG117650594 Astra Bioplant LTD,

23 Bulgaria str,

7060 Slivo Pole, Bulgaria

VAT: BG117650594

Port of loading: IZMAIL, UKRAINE
Port of discharge: Rousse, Bulgaria

Vessel Tanks Nos.: BB1, SB1, BB2, SB2, BB4, SB4, BB5, SB5

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N° N°	Last cargo	Second Last Cargo	Third Last Cargo
BB1 65 GISS	Waciss CISS SFS SFS CISS CISS	S CISS CISS CISS CISS CISS CISS CISS CI	SFS CISS CISS CISS CISS
SB1 SB1	SFS CISS CISS CISS CISS CISS	SS CAS CISS CISS CISS CISS CISS CISS	SFS CISS CAS CISS CAS CISS
BB2	to CISS CISS CISS CISS CISS CISS	S CAS CISS CISS CISS CISS CISS CISS CISS	SFS Class Cl
SB2	SECURE CISS SESSIONS CISS CISS	S DAS CHASE SFS SONS CHASE	SFS SFS
BB4	SFS SFS	SFS	SFS SFS
SB4	SFS	SFS	SFS
BB5	SFS	SFS	SFS SFS
MILLE SB5	SFS	SFS	SFS of International S

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.







2/2

CISS Group PTE. LTD. 10, Anson Road, #29-05 A, International Plaza, Singapore, 079903. e-mail: inspection@ciss-group.com

CERTIFICATE No.: UA01385

ORIGINAL

This certificate is electronically signed and stamped. DATED: 30th of SEPTEMBER, 2022 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA







This certificate is issued to any job or services carried out within the GENERAL TERMS AND CONDITION OF BUSINESS printed overleaf. This certificate is not intended to relieve the parties of any relevant sales contract from their contractual obligations. The Company's responsibility under this Certificate is limited to proven negligence and will in no case be more then ten times the amount of the fees.