



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciis-group.com

CERTIFICATE No.: UA01428

ORIGINAL

## TANK CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL IN BULK  
Vessel: MT MUBARIZ IBRAHIMOV  
Quantity: 6604,180 MT  
B/L No. & Date: NO. 1, 2, 3 DD 30.10.2022  
Shipper: «PIVDENNIY PEREVALOCHNIY KOMPLEKS» LLC  
Ukraine, Odessa region, Izmail, Aerodromne shosse, 2 zh  
ON BEHALF OF T B B TRADING DMCC  
LLC "GOLDMAIS"  
21037, UKRAINE, VINNITSA, PIROGOV STREET, 148.  
ON BEHALF OF T B B TRADING DMCC  
Consignee: TO ORDER  
Notify address: T B B TRADING DMCC  
UNIT 1909 JUMEIRAH BAY 2 PLOT JLT-PH2-X2A JUMEIRAH  
LAKES TOWERS DUBAI, UAE  
Port of loading: IZMAIL, UKRAINE  
Port of discharge: SEVILLE, SPAIN  
Vessel Tanks Nos.: 1C, 2C, 3C, 4C, 5C, 6C

### RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1C	CSFSO 84%	CSFSO 84%	CSFSO 73%
2C	CSFSO 94%	CSFSO 94%	CSFSO 94%
3C	CSFSO 93%	CSFSO 93%	CSFSO 94%
4C	CSFSO 94%	CSFSO 94%	CSFSO 95%
5C	CSFSO 92%	CSFSO 92%	CSFSO 94%
6C	CSFSO 92%	CSFSO 92%	CSFSO 95%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

**This certificate is electronically signed and stamped.**

DATED: 30th of OCTOBER, 2022

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA

