



**CISS Group PTE. LTD.**

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

**CERTIFICATE No.: UA01447**

**ORIGINAL**

## **TANK CLEANLINESS CERTIFICATE**

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

|                       |   |
|-----------------------|---|
| Description of goods: | UKRAINIAN ORIGIN CRUDE SUNFLOWERSEED OIL, IN BULK   |
| Vessel:               | MT MRC HATICE ANA   |
| Quantity:             | 3797,240 MT   |
| B/L No. & Date:       | NO. 2 DD 20.11.2022   |
| Shipper:              | LLC "SVITANOKORP"<br>65089, Ukraine, Odesa, street Academician Williamsa,<br>bldg. 59-E, r. 11<br>ON BEHALF OF T B B TRADING DMCC<br>TO ORDER<br>T B B TRADING DMCC<br>UNIT 1909 JUMEIRAH BAY 2 PLOT<br>JLT-PH2-X2A JUMEIRAH<br>LAKES TOWERS DUBAI, UAE |
| Consignee:            |   |
| Notify address:       |   |
| Port of loading:      | IZMAIL, UKRAINE   |
| Port of discharge:    | SEVILLE, SPAIN  |
| Vessel Tanks Nos.:    | 1P, 1S, 2P, 2S, 3P, 3S, 4P, 4S, 5P, 5S, 6P, 6S, DECK P, DECK S  |

### **RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

| Ships Tanks N° | Last cargo | Second Last Cargo | Third Last Cargo |
|----------------|------------|-------------------|------------------|
| 1P             | VEGOIL 97% | GASOIL 97%        | GASOLINE 97%     |
| 1S             | VEGOIL 97% | GASOIL 97%        | GASOLINE 97%     |
| 2P             | VEGOIL 90% | GASOIL 97%        | GASOLINE 97%     |
| 2S             | VEGOIL 92% | GASOIL 97%        | GASOLINE 97%     |
| 3P             | VEGOIL 96% | GASOIL 97%        | GASOLINE 97%     |
| 3S             | VEGOIL 96% | GASOIL 97%        | GASOLINE 97%     |
| 4P             | VEGOIL 96% | GASOIL 97%        | GASOLINE 97%     |
| 4S             | VEGOIL 96% | GASOIL 97%        | GASOLINE 97%     |
| 5P             | VEGOIL 95% | GASOIL 97%        | GASOLINE 97%     |
| 5S             | VEGOIL 95% | GASOIL 97%        | GASOLINE 97%     |
| 6P             | VEGOIL 76% | GASOIL 97%        | GASOLINE 97%     |
| 6S             | VEGOIL 76% | GASOIL 97%        | GASOLINE 97%     |
| DECK P         | VEGOIL 95% | GASOIL 95%        | GASOLINE 95%     |
| DECK S         | VEGOIL 95% | GASOIL 95%        | GASOLINE 95%     |

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

**This certificate is electronically signed and stamped.**

**DATED: 20th of NOVEMBER, 2022**

**For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA**

