



Commodities International  
Shipping and Survey



Page

1/1

CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

CERTIFICATE No.: UA01501

ORIGINAL

## TANK CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN ORIGIN CRUDE SUNFLOWER OIL  
Vessel: MT BARBAROS ULUC VARDAL  
Quantity: 2452,320 MT  
B/L No. & Date: NO. 3 DD 27.01.2023  
Shipper: LIMITED LIABILITY COMPANY «METROCITY»  
65490, UKRAINE, ODESSA REG., ODESSA AREA,  
TEPLODAR, AVENUE ENERGETYKIV, BLD. 73, OF. 1  
ON BEHALF OF D.A.M TRADE GROUP LLC  
Consignee: TO ORDER  
Notify address: SAYINLAR GIDA MADDELERİ SANAYİ VE TİCARET A.Ş.  
3. Organize Sanayi Bölgesi 83303 nolu cadde no:3  
Şehitkamil – GAZİANTEP  
Port of loading: IZMAIL, UKRAINE  
Port of discharge: HATAY, DÖRTYOL, GÜNEY WINBA  
Vessel Tanks Nos.: 1S, 2P/S, 3P/S, 4P/S, 5P/S

### RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

| Ships Tanks N° | Last cargo | Second Last Cargo | Third Last Cargo   |
|----------------|------------|-------------------|--------------------|
| 1S             | ULSD 94%   | GASOLINE 95%      | CRUDE PALM OIL 88% |
| 2P             | ULSD 95%   | GASOLINE 95%      | CRUDE PALM OIL 89% |
| 2S             | ULSD 95%   | GASOLINE 96%      | CRUDE PALM OIL 89% |
| 3P             | ULSD 88%   | GASOLINE 95%      | CRUDE PALM OIL 84% |
| 3S             | ULSD 88%   | GASOLINE 95%      | CRUDE PALM OIL 85% |
| 4P             | ULSD 94%   | GASOLINE 95%      | CRUDE PALM OIL 89% |
| 4S             | ULSD 94%   | GASOLINE 95%      | CRUDE PALM OIL 90% |
| 5P             | ULSD 94%   | GASOLINE 85%      | CRUDE PALM OIL 89% |
| 5S             | ULSD 94%   | GASOLINE 85%      | CRUDE PALM OIL 89% |

These findings are valid for the time and place of inspection only.  
The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 27th of JANUARY, 2023

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA

