



Commodities International  
Shipping and Survey



CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: UA01519

ORIGINAL

## LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN ORIGIN CRUDE SUNFLOWERSEED OIL
Vessel:	MT VITIS
Quantity:	5879,338 MT
B/L No. & Date:	NO. 1 DD 16.03.2023
Shipper:	LIMITED LIABILITY COMPANY "INVEKS GROUP" 02132, UKRAINE, KYIV, AVE. BAZHANA MIKOLI, 151, OFF.37 ON BEHALF OF ACRO TRADE GLOBAL FZE
Consignee:	TO ORDER
Notify address:	ARAM NISASTA YAG HUBUBAT SAN VE TIC AS GOMMETAS MAH URFA BLV FORD TRUCK DIYARBAKIR BAYI BLOK NO:273 BAGLAR-DIYARBAKIR, TURKEY
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	MERSIN OR ISKENDERUN OR CEYHAN PORT OR IZMIR PORT OR MARMARA PORT, TURKEY
Vessel Tanks Nos.:	1P, 1S, 2P, 2S, 3P, 3S, 4P, 4S, 5P, 5S, 6P, 6S, 7P, 7S, 8P, 8S, 9P, 9S, 10P, 10S, 11P, 11S

## RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
1S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
2P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
2S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
3P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
3S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
4P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
4S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
5P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
5S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
6P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
6S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
7P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
7S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
8P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
8S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
9P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
9S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
10P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
10S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
11P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
11S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 16th of MARCH, 2023

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA

