

CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciis-group.com

CERTIFICATE No.: UA01522

ORIGINAL

CERTIFICATE OF CLEANLINESS SHIP'S TANK

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

CRUDE SUNFLOWER SEED OIL UKRAINE ORIGIN, IN BULK FOR FOOD USE AFTER APPROPRIATE REFINING

Vessel:

MT VITIS

Quantity:

5857,990 MT

B/L No. & Date:

NO.1 AND 2 DD 14.04.2023

Shipper:

LIMITED LIABILITY COMPANY "TERMINAL ESTATE"
UKRAINE, 49000, DNIPROPETROVSK REGION,
DNIPIRO CITY, DMYTRO YAVORNYTSKYI AVE., BUILDING 76A
REG. NUMBER 450344159

Consignee:

ON BEHALF OF GREEN CAPITAL FZE

Notify address:

«IZMAILSKA TORGובה COMPANIA» LLC

Port of loading:

Ukraine, Odesa region, Izmail, Aerodromne shosse, 2 zh

Port of discharge:

ON BEHALF OF GREEN CAPITAL FZE

Vessel Tanks Nos.:

TO THE ORDER

CASA OLEARIA ITALIANA S.P.A

VIA BAIONE 200

70043 MONOPOLI (BARI)

IZMAIL, UKRAINE

MONOPOLI, ITALY

1P, 1S, 2P, 2S, 3P, 3S, 4P, 4S, 5P, 5S, 6P, 6S, 7P, 7S,
8P, 8S, 9P, 9S, 10P, 10S, 11P, 11S**RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

Ships Tanks	Nº	Last cargo	Second Last Cargo	Third Last Cargo
	1P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
	1S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
	2P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
	2S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
	3P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
	3S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL





CERTIFICATE No.: UA01522

ORIGINAL

4P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
4S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
5P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
5S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
6P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
6S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
7P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
7S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
8P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
8S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
9P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
9S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
10P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
10S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
11P	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL
11S	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL	CRUDE SUNFLOWER OIL

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 14th of APRIL, 2023

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

