







Page

1/1

CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)

 Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 Inspection@ciss-group.com

**CERTIFICATE No.: UA01586** 

**ORIGINAL** 

## **LAST 3 CARGOES CERTIFICATE**

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: CRUDE SUNFLOWER SEED OIL, IN BULK, UKRAINIAN ORIGIN

Vessel: MT SES 1
Quantity: 2405,140 MT

B/L No. & Date: NO. 1 AND 2 DD 14.10.2023

Shipper: «IZMAILSKA TORGOVA COMPANIA» LLC

UKRAINE, ODESA REGION, IZMAIL,

AERODROMNE SHOSSE, 2ZH

ON BEHALF OF D.A.M TRADE GROUP LLC

«CRYSTAL ALLIANCE TRADE» LLC 68600, Ukraine, Odesa region, Izmail,

st. Verbytskyi Mykhailo 11

ON BEHALF OF D.A.M TRADE GROUP LLC

Consignee: TO ORDER

Notify address: AGRIVIA OIL EOOD

AP. 76, FL.3, ENT.E, BL. 615, 2 VRABNICA,

SOFIA BULGARIA VAT №BG205836122

Port of loading: IZMAIL, UKRAINE
Port of discharge: VARNA, BULGARIA

Vessel Tanks Nos.: 1C, 2P, 3P, 4P, 5P, 6P, 7P, 2S, 3S, 4S, 5S, 6S, 7S

## **RESULTS OF INSPECTION**

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	Last cargo	SECOND LAST CARGO	THIRD LAST CARGO
1C	GASOIL 98%	SFSO 98%	ULSD 98%
2P	GASOIL 98%	SFSO 98%	ULSD 98%
2S	GASOIL 98%	SFSO 98%	ULSD 98%
3P	GASOIL 98%	SFSO 98%	ULSD 98%
38	GASOIL 98%	SFSO 98%	ULSD 98%
4P	GASOIL 98%	SFSO 98%	ULSD 98%
4S	GASOIL 98%	SFSO 98%	ULSD 98%
5P	GASOIL 98%	SFSO 98%	ULSD 98%
5S	GASOIL 98%	SFSO 98%	ULSD 98%
6P	GASOIL 98%	SFSO 98%	ULSD 98%
6S	GASOIL 98%	SFSO 98%	ULSD 98%
7P	GASOIL 98%	SFSO 98%	ULSD 98%
7S	GASOIL 98%	SFSO 98%	ULSD 98%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.



DATED: 14th of OCTOBER, 2023
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA





