

**CERTIFICATE No.: UA01592/1** 





CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore)

5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

**ORIGINAL** 

## ORIGINAL TANK INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

CRUDE SUNFLOWER OIL Description of goods:

Vessel: MT HIRA V Quantity: 3000,000 MT

B/L No. & Date: NO. 1 DD 04.11.2023

«ODESKA TORGOVA KOMPANIA» LLC Shipper:

UKRAINE, ODESSA REGION, ODESSA, CHURCH STR., 19

ON BEHALF OF GREEN CAPITAL FZE

Consignee: TO ORDER

Notify address: Kadooğlu Yağ San. Ve Tic.A.Ş.

4. Organize Sanayi Bölgesi 83422 Nolu Cad.

No: 11 Şehitkamil - GAZİANTEP

Port of loading: IZMAIL, UKRAINE Port of discharge: **GUNEY WIMBA** 

SLOP C, 1P, 2P, 3P, 4P, 5P, 6P, 1S, 2S, 3S, 4S, 5S, 6S Vessel Tanks Nos.:

## **RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

and the second s			
SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	CSFO A	MTBE	CSFO
1S	CSFO	MTBE	CSFO
2P	CSFO	MTBE	CSBO
2S	CSFO	MTBE	CSBO
3P	CSFO	MTBE	CSFO
3S	CSFO	MTBE	CSFO
4P	CSFO	MTBE	CSBO
4S	CSFO	MTBE	CSBO
5P	CSFO	MTBE	CSFO
5S	CSFO	MTBE	CSFO
6P	CSFO	MTBE	CSFO
6S	CSFO	MTBE	CSFO
SLOP C	CSFO	MTBE	CSFO

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 4th of NOVEMBER, 2023 For and on behalf of CISS GROUP Ukraine LLC Registered Superintendent and Surveyor Member of FOSFA





