



CISS GROUP UKRAINE LLC
member of CISS GROUP Pte.Ltd. (Singapore)
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciss-group.com

CERTIFICATE No.: UA01599

ORIGINAL

LAST 3 CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWER SEED OIL, IN BULK, UKRAINIAN ORIGIN
Vessel:	MT SES 1
Quantity:	2408,350 MT
B/L No. & Date:	NO. 1 AND 2 DD 31.10.2023
Shipper:	«IZMAILSKA TORGHOVAYA KOMPANIYA» LLC UKRAINE, ODESA REGION, IZMAIL, AERODROMNE SHOSSE, 2ZH ON BEHALF OF D.A.M TRADE GROUP LLC «CRYSTAL ALLIANCE TRADE» LLC 68600, Ukraine, Odesa region, Izmail, st. Verbytskyi Mykhailo 11 ON BEHALF OF D.A.M TRADE GROUP LLC
Consignee:	TO ORDER
Notify address:	AGRIVIA OIL EOOD AP. 76, FL.3, ENT.E, BL. 615, 2 VRABNICA, SOFIA BULGARIA VAT №BG205836122
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	VARNA, BULGARIA
Vessel Tanks Nos.:	1C, 2P, 3P, 4P, 5P, 6P, 7P, 2S, 3S, 4S, 5S, 6S, 7S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1C	SFSO 98%	GASOIL 98%	SFSO 98%
2P	SFSO 98%	GASOIL 98%	SFSO 98%
2S	SFSO 98%	GASOIL 98%	SFSO 98%
3P	SFSO 98%	GASOIL 98%	SFSO 98%
3S	SFSO 98%	GASOIL 98%	SFSO 98%
4P	SFSO 98%	GASOIL 98%	SFSO 98%
4S	SFSO 98%	GASOIL 98%	SFSO 98%
5P	SFSO 98%	GASOIL 98%	SFSO 98%
5S	SFSO 98%	GASOIL 98%	SFSO 98%
6P	SFSO 98%	GASOIL 98%	SFSO 98%
6S	SFSO 98%	GASOIL 98%	SFSO 98%
7P	SFSO 98%	GASOIL 98%	SFSO 98%
7S	SFSO 98%	GASOIL 98%	SFSO 98%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 31st of OCTOBER, 2023

**For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA**

