member of CISS GROUP Pte.Ltd. (Singapore)

CISS GROUP UKRAINE LLC

inspection@ciss-group.com

5, Odessa Blv., Ovidiopol district,

Lymanka village, Odessa region, 65037







**CERTIFICATE No.: UA01662** 

**ORIGINAL** 

## TANK CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we

hereby confirm as follows:

Description of goods: UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL, IN BULK

Vessel: MT SCOT BAYERN

Quantity: 6553,670 MT

B/L No. & Date: NO. 1 DD 29.02.2024

Shipper: "ODESKA TORGOVA KOMPANIA" LLC

Address: Ukraine, Odesa region, Odesa, Church str.,19

ON BEHALF OF DAM TRADE GROUP LLC

Consignee: TO ORDER

Notify address: REKA BITKISEL YAGLAR SAN. VE TIC. A.S.

Barbaros Mah. Morsümbül Sok. No:1 Varyap Meridian Business

I Blok Kat:6 Ofis 81-87 Batı Ataşehir 34746

Phone: +90 216 687 17 00 - Fax: +90 216 687 17 10

Port of loading: IZMAIL, UKRAINE

Port of discharge: TEKIRDAG PORT / TURKEY

Vessel Tanks Nos.: 1P,2P,3P,4P,5P,6P,7P,1S,2S,3S,4S,55,6S,7S.

## **RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	ULSD 91,9%	SFSO 88,6%	// ULSD 90,4%
1S	ULSD 92,6%	SFSO 89,1%	ULSD 91,5%
2P	ULSD 93,3%	SFSO 72,5%	ULSD 91,7%
2S	ULSD 92,7%	SFSO 72,0%	ULSD 91,0%
-3P	ULSD 92,0%	SFSO 83,2%	ULSD 90,2%
3S	ULSD 92,0%	SFSO 83,3%	ULSD 93,3%
4P	ULSD 91,4%	SFSO 78,7%	ULSD 91,4%
4S as class class cas	ULSD 92,2%	SFSO 79,2%	ULSD 92,8%
5P Cas cas cas	Class class criss on ULSD 89,8%	SFSO 75,0%	ULSD 89,4%
5S	ULSD 89,8%	SFSO 76,0%	ULSD 91,7%
6Pcss css css css	ULSD 77,5%	SFSO 80,5%	ULSD 81,2%
6S CASS CHEST CHES	Cas as all ULSD 77,1%	SFSO 80,0%	ULSD 80,8%
7P	ULSD 70,5%	SFSO 66,8%	ULSD 70,5%
7S	ULSD 72,3%	SFSO 68,4%	ULSD 72,4%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

F

DATED: 29th of FEBRUARY, 2024
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA



