



CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciss-group.com

CERTIFICATE No.: UA01663

ORIGINAL

## TANK CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: Crude Sunflower Oil in bulk. Taric Code 15121110  
 Vessel: MT DB RUSE  
 Quantity: 992,110 MT  
 B/L No. & Date: NO. 1 DD 12.02.2024  
 Shipper: "ODESKA TORGHOVAYA KOMPANIYA" LLC  
 Ukraine, Odesa region, Odesa, Church str., 19  
 ON BEHALF OF D.A.M TRADE GROUP LLC  
 Consignee: To Order of First Investment Bank  
 111 P Tsarigradsko shose Blvd., 1784 Sofia  
 BIC / SWIFT: FINVBGSF ("Bank")  
 Notify address: Astra Bioplant Trading S.A.  
 RUE DU NANT 6  
 1207 GENEVA SWITZERLAND  
 Port of loading: IZMAIL, UKRAINE  
 Port of discharge: Constanta, Romania  
 Vessel Tanks Nos.: 1P,1S,2P,2S,3P,3S,4P,4S,5P,5S

### RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	CSFSO	CSFSO	CSFSO
1S	CSFSO	CSFSO	CSFSO
2P	CSFSO	CSFSO	CSFSO
2S	CSFSO	CSFSO	CSFSO
3P	CSFSO	CSFSO	CSFSO
3S	CSFSO	CSFSO	CSFSO
4P	CSFSO	CSFSO	CSFSO
4S	CSFSO	CSFSO	CSFSO
5P	CSFSO	CSFSO	CSFSO
5S	CSFSO	CSFSO	CSFSO

**Remarks:** Cargo tanks 1P,1S,2P,2S,3P,3S,4P,4S,5P,5S are not washed. During tank inspection were found residues of previous cargo in a.m. cargo tanks

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 12th of FABRUARY, 2024

For and on behalf of CISS GROUP Ukraine LLC  
 Registered Superintendent and Surveyor Member of FOSFA

