



**Commodities International
Shipping and Survey**



**FOSFA
INTERNATIONAL**

Page 1/2

CISS GROUP UKRAINE LLC
member of **CISS GROUP Pte.Ltd. (Singapore)**
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: UA01725

ORIGINAL

Load Compartments Inspection report (LCI) according to GMP +Certification Scheme for the Animal Feed Sector

We, CISS GROUP Ukraine LLC, herewith report on the loading Compartments Inspection carried out for following cargo/shipment in accordance with the instructions received and relevant instructions and the stipulation of the GMP Transport code

Shipment of	BL	NO. 1 DD 17.07.2024
	Quantity	3231,270 MT
To be load on board	M/V DIMAIZO	Flag
		PANAMA Year built 2007
Expected to be Loadready, date	16.07.2024	At Place
		IZMAIL, UKRAINE, terminal DSR
Principals "CRYSTAL ALLIANCE TRADE" LLC	Acting as	-
Sellers / Suppliers	"ODESKA TORGOVA KOMPANIA" LLC UKRAINE, ODESA REGION, ODESA, CHURCH STR.,19 ON BEHALF OF GREEN CAPITAL FZE	
Start of loading Foreseen abt	16.07.2024	Stev / Terminal
		pier 3
Remarks		
Owner / Agent	KESMA SHIPPING/SOF MARINE	
Type of vessel	General cargo	

The cargo as described above has to be loaded in the following cargo compartments

Hold	Cargo tbl	Quantity tbl	Previously Loaded cargos			
			First last cargo	Second last cargo	Third last cargo	Fourth last cargo
1	Ukrainian Sunmeal Pellets in bulk	1540	Wheat in bulk	Steel Products	Urea in bulk	Steel Products
2	Ukrainian Sunmeal Pellets in bulk	1610	Wheat in bulk	Steel Products	Urea in bulk	Steel Products

Previous three loads carried in the loading compartment(s) and any subsequent cleaning activities, which are in accordance with the IDTF (International Database Transport (for) Feed), www.icrt-idtf.com



This certificate is issued to any job or services carried out within the GENERAL TERMS AND CONDITION OF BUSINESS printed overleaf. This certificate is not intended to relieve the parties of any relevant sales contract from their contractual obligations. The Company's responsibility under this Certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees.



**Commodities International
Shipping and Survey**



**FOSFA
INTERNATIONAL**

Page 2/2

CISS GROUP UKRAINE LLC
member of **CISS GROUP Pte.Ltd. (Singapore)**
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: UA01725

ORIGINAL

Cleaning procedure as declared by ship's Master							
CLEANING	LEVEL A	DRY					YES/NO
	LEVEL B	WITH WATER					YES/NO
	LEVEL C	WATER+DETERGENT					YES/NO
	LEVEL D	WATER+DETERGENT+DESINFECTANT					YES/NO
Method of cleaning for each previous voyage							
Previously Loaded cargos				Method of cleaning			
First last cargo				LEVEL B			
Second last cargo				LEVEL B			
Third last cargo				LEVEL B			
Fourth last cargo				LEVEL B			
The LCI was carried out at (place)		Izmail / M/V DIMAIZO		Date	16.07.2024		
Started		16:30 hrs		Finished	17:30 hrs		

The results of inspection are valid for the time and place of inspection only.

This certificate is electronically signed and stamped.

DATED: 17th of JULY, 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of GAFTA



This certificate is issued to any job or services carried out within the GENERAL TERMS AND CONDITION OF BUSINESS printed overleaf. This certificate is not intended to relieve the parties of any relevant sales contract from their contractual obligations. The Company's responsibility under this Certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees.