



**Commodities International
Shipping and Survey**



**FOSFA
INTERNATIONAL**

Page

1/1

CISS GROUP UKRAINE LLC
member of **CISS GROUP Pte.Ltd. (Singapore)**
5, Odessa Blv., Ovidiopol district,
Lymanka village, Odessa region, 65037
inspection@ciiss-group.com

CERTIFICATE No.: UA01727

ORIGINAL

CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Shipper: "CRYSTAL ALLIANCE TRADE" LLC
68600, UKRAINE, ODESA REGION, IZMAIL,
ST.VERBYTSKYI MYKHAILO 11
Consignee: TO ORDER
Description of goods: CRUDE SUNFLOWER SEEDS OIL IN BULK
Shore tank: Land Tank 3
Place of loading: IZMAIL, UKRAINE / "UPSS IZMAIL" LLC

RESULTS OF INSPECTION

THIS IS TO CERTIFY that prior to loading operations we inspected the following cargo tanks:

Land Tank 3

Based on visual inspection the above tank was found suitable for loading of above mentioned cargo.

Air tests: -

Heat coils/exchanger: -

Vessel's pumps: -

Vessel's lines: -

Inspected as far as it was possible and accessible and found to be in apparently good condition.

Land Tank passed inspection: 19.07.2024 at 10:00 hrs lt.

Remarks: Sea valve sealed: N/A

Well drained only.

These findings are valid for the time and place of inspection only.

This certificate is electronically signed and stamped.

DATED: 22nd of JULY, 2024

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA

