



Commodities International  
Shipping and Survey



Page

1/1

CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

CERTIFICATE No.: UA01904

ORIGINAL

## HOLDS CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	CRUDE SUNFLOWER OIL IN BULK CROP 2024
Vessel:	MT STELLAR
Quantity:	5021,450 MT
B/L No. & Date:	NO. 1 DD 14.03.2025
Shipper:	«IZMAILSKA TORGOVA COMPANIA» LLC Ukraine, Odesa region, Izmail, Aerodromne shosse, 2 zh ON BEHALF OF D.A.M TRADE GROUP LLC on behalf of "Maestro-Nut" SRL1/9 Bucovina str., mun. Chisinau, MD4839, Republic of Moldova on behalf of EMPRIO A G M GENERAL TRADING L.L.C UAE DUBAI, Building Name BIN DASMAL BUILDING, Al Goze Industrial First, P/N 55-0, Land DM No 364-595
Consignee:	TO ORDER
Notify address:	SPIROCO S.A.R.L El murr bldg 61, Senegal street, Karantina region, Beirut - Lebanon.
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	TRIPOLI, LEBANON
Vessel Tanks Nos.:	1P, 2P, 3P, 4P, 5P, 6P, 1S, 2S,3S, 4S, 5S, 6S

## RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry the oil. The last three cargoes as declared by the vessel are as follows:

SHIPS TANKS N°	LAST CARGO	SECOND LAST CARGO	THIRD LAST CARGO
1P	ULSD 10 PPM 97,8%	ULSD 10 PPM 97,8%	ULSD 10 PPM 97,9%
1S	ULSD 10 PPM 98,7%	ULSD 10 PPM 97,8%	ULSD 10 PPM 98,1%
2P	ULSD 10 PPM 97,8%	ULSD 10 PPM 97,8%	ULSD 10 PPM 97,8%
2S	ULSD 10 PPM 98,2%	ULSD 10 PPM 98,1%	ULSD 10 PPM 98,0%
3P	ULSD 10 PPM 98,0%	ULSD 10 PPM 97,8%	ULSD 10 PPM 97,8%
3S	ULSD 10 PPM 98,1%	ULSD 10 PPM 98,1%	ULSD 10 PPM 98,0%
4P	ULSD 10 PPM 95,8%	ULSD 10 PPM 98,0%	ULSD 10 PPM 97,9%
4S	ULSD 10 PPM 95,0%	ULSD 10 PPM 97,8%	ULSD 10 PPM 97,9%
5P	ULSD 10 PPM 97,7%	ULSD 10 PPM 97,8%	ULSD 10 PPM 97,8%
5S	ULSD 10 PPM 98,0%	ULSD 10 PPM 97,8%	ULSD 10 PPM 97,8%
6P	ULSD 10 PPM 98,0%	ULSD 10 PPM 98,2%	ULSD 10 PPM 97,7%
6S	ULSD 10 PPM 98,2%	ULSD 10 PPM 97,8%	ULSD 10 PPM 97,8%

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 14th of MARCH, 2025

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA

