



Page 1/1

CISS Group PTE. LTD.
10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciss-group.com

**CERTIFICATE No.: SGD00412** 

**ORIGINAL** 

## TANK CLEANLINESS CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

RUSSIAN CRUDE SUNFLOWERSEED OIL, IN BULK

Vessel:

MT "GLORIA"

Quantity:

6.000,040 MT

B/L No. & Date:

Nos. 1 dd 16.04.2020

Shipper:

"TRADE HOUSE CHERNOZEMYE" LLC, OFFICE 409, 2,

PETER THE GREAT SQ, LIPETSK, 398001, RUSSIA

TO ORDER

Notify address:

Consignee:

Pier Agro Gıda San. Ve Tic.A.Ş.

Adana Yumurtalık Serbest Bölge Şb.

Sarımazı Serbest Bölge Mah.

Adana Yumurtalık Serbest Bölgesi

Ceyhan - ADANA-TURKEY

Port of loading:

KAVKAZ, RUSSIA TOROS PORT

Port of discharge: Vessel Tanks Nos.:

1P/S, 2P/S, 3P/S, 4P/S, 5P/S, 6P/S

## **RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry:

## CRUDE SUNFLOWERSEED OIL

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 21 OF APRIL, 2020 FOR AND ON BEHALF OF CISS GROUP Ukraine LLC

REGISTERED SUPERINTENDENT MEMBER OF FOSF





