

FOSFA NTERNATIONAL

**Page 1/1** 

CISS Group PTE. LTD.
10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciss-group.com

**CERTIFICATE No.: SGD00415** 

**ORIGINAL** 

## TANK CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

RUSSIAN CRUDE SUNFLOWERSEED OIL, IN BULK

Vessel:

MT "TRUVOR"

Quantity:

6020,918 MT

B/L No. & Date:

No. 1 dd 29.04.2020

Shipper:

"Trade House "Chernozemye" LLC, office 409, 2, Peter the

Great Sq., Lipetsk, 398001, Russia

Consignee:

TO ORDER

Notify address:

UNAT YAĞ GIDA SANAYİ VE TİCARET A.Ş

**15 TEMMUZ MAH.148168 NOLU SOKAK NO:14** 

**ŞEHİTKAMİL/GAZİANTEP** 

TEL:0 342 337 99 09 FAKS:0342 337 99 05

Port of loading: Port of discharge: PORT KAVKAZ, RUSSIA MERSIN PORT, TURKEY

Vessel Tanks Nos.:

Tank 1, Tank 2, Tank 3, Tank 4, Tank 5, Tank 6, Tank 7, Tank

8, Tank 9, Tank 10, Tank 11, Tank 12

## **RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry:

## 

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 29 OF APRIL, 2020 FOR AND ON BEHALF OF CISS GROUP Ukraine LLC FIRST CLASS INDEPENDENT SURVEYOR REGISTERED SUPERINTENDENT MEMBER OF FOSFA





