

Gafta

FOSFA INTERNATIONAL

Page 1/1

CISS Group PTE. LTD.
10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciss-group.com

CERTIFICATE No.: SGD00425

ORIGINAL

TANK CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

RUSSIAN CRUDE SUNFLOWERSEED OIL, IN BULK

Vessel: Quantity: M/T "GARMONIA" 6 002.760 MT

B/L No. & Date:

No 1 dd 01.06.2020

Shipper:

"Trade House "Chernozemye" LLC, office 413, 3,

Peter the Great Sq., Lipetsk, 398001, Russia

Consignee:

TO ORDER

Notify address:

Port of loading:

Pier Agro Gıda San. Ve Tic.A.Ş.

Adana Yumurtalık Serbest Bölge Şb.

Sarımazı Serbest Bölge Mah.

Adana Yumurtalık Serbest Bölgesi

Ceyhan - ADANA

port Kavkaz, Russia

TOROS port, Turkey

Port of discharge: Vessel Tanks Nos.:

1p/s, 2p/s, 3p/s, 4p/s, 5p/s, 6p/s

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry:

RUSSIAN CRUDE SUNFLOWERSEED OIL, IN BULK

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 02 OF JUNE, 2020 FOR AND ON BEHALF OF CISS GROUP Ukraine LLC FIRST CLASS INDEPENDENT SURVEYOR REGISTERED SUPERINTENDENT MEMBER OF FOSFA





