



**Commodities International
Shipping and Survey**



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciiss-group.com

Page 1/1

**CERTIFICATE No.: SGD00426
ORIGINAL**

LAST THREE CARGO CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

Vessel:

Quantity:

B/L No. & Date:

Shipper:

Consignee:

Notify address:

Port of loading:

Port of discharge:

Vessel Tanks Nos.:

CRUDE SUNFLOWER SEED OIL IN BULK

M/T "AURA"

6 002,570 MT

No 1 dd 06.06.2020

Trade House "Chernozemye" LLC, office 413, 3,

Peter the Great Sq., Lipetsk, 398001, Russia

TO ORDER

Pier Agro Gıda San. Ve Tic.A.Ş.

Adana Yumurtalık Serbest Bölge Şb.

Sarımsazı Serbest Bölge Mah.

Adana Yumurtalık Serbest Bölgesi

Ceyhan - ADANA

port Kavkaz, Russia

TOROS port, Turkey

1p/s, 2p/s, 3p/s, 4p/s, 5p/s, 6p/s

RESULTS OF INSPECTION

As per Captain of said vessel information the previous cargoes carried in the tanks, lines and pump systems were some substances which:

LAST THREE CARGOES CARRIED ARE AS FOLLOWS:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	DIESEL EURO 10PPM	GASOIL 10PPM	CSFSO
1S	DIESEL EURO 10PPM	GASOIL 10PPM	CSFSO
2P	DIESEL EURO 10PPM	GASOIL 10PPM	CSFSO
2S	DIESEL EURO 10PPM	GASOIL 10PPM	CSFSO
3P	DIESEL EURO 10PPM	GASOIL 10PPM	CSFSO
3S	DIESEL EURO 10PPM	GASOIL 10PPM	CSFSO
4P	DIESEL EURO 10PPM	GASOIL 10PPM	CSFSO
4S	DIESEL EURO 10PPM	GASOIL 10PPM	CSFSO
5P	DIESEL EURO 10PPM	GASOIL 10PPM	CSFSO
5S	DIESEL EURO 10PPM	GASOIL 10PPM	CSFSO
6P	DIESEL EURO 10PPM	EMPTY	CSFSO
6S	DIESEL EURO 10PPM	EMPTY	CSFSO

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties

DATED: 07 OF JUNE, 2020.

FOR AND ON BEHALF OF

CISS GROUP Ukraine LLC

REGISTERED SUPERINTENDENT MEMBER OF FOSFA

