



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.  
e-mail: inspection@ciss-group.com

## LAST THREE CARGO CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

CRUDE SUNFLOWER SEED OIL IN BULK

Vessel:

M/T "KURA RIVER"

Quantity:

2 996, 272 MT

B/L No. & Date:

No 1 dd 16.06.2020

Shipper:

Trade House "Chernozemye" LLC, office 413, 3,

Consignee:

Peter the Great Sq., Lipetsk, 398001, Russia

Notify address:

TO ORDER

Port of loading:

PAM YAG GIDA VE KIMYA SANAYI VE TICARET LTD STI (TAX

Port of discharge:

NUMBER 720 007 0609)

Vessel Tanks Nos.:

SEKİLİ MAHALLESİ, E-90 KARAYOLU CADDE, NO :19/1 , NIZIP  
GAZIANTEP 27700, TURKIYE

port Kavkaz, Russia

Mersin port, Turkey

1, 2, 3, 4, 5, 6

### RESULTS OF INSPECTION

As per Captain of said vessel information the previous cargoes carried in the tanks, lines and pump systems were some substances which:

#### LAST THREE CARGOES CARRIED ARE AS FOLLOWS:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil
2	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil
3	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil
4	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil
5	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil
6	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties

DATED: 17 OF JUNE, 2020.

FOR AND ON BEHALF OF  
CISS GROUP Ukraine LLC

REGISTERED SUPERINTENDENT MEMBER OF FOSFA

