



Commodities International
Shipping and Survey



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: SGD00431/2
ORIGINAL

LAST THREE CARGO CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

Vessel:

Quantity:

B/L No. & Date:

Shipper:

Consignee:

Notify address:

Port of loading:

Port of discharge:

Vessel Tanks Nos.:

CRUDE SUNFLOWER SEED OIL IN BULK

M/T "KURA RIVER"

2 996, 271 MT

No 2 dd 16.06.2020

Trade House "Chernozemye" LLC, office 413, 3,

Peter the Great Sq., Lipetsk, 398001, Russia

TO ORDER

UNAT YAĞ GIDA SANAYİ VE TİCARET A.Ş

15 TEMMUZ MAH.148168 NOLU SOKAK NO:14

ŞEHİTKAMİL/GAZİANTEP

TEL:0 342 337 99 09 FAKS:0342 337 99 05

port Kavkaz, Russia

Mersin port, Turkey

1, 2, 3, 4, 5, 6, 7

RESULTS OF INSPECTION

As per Captain of said vessel information the previous cargoes carried in the tanks, lines and pump systems were some substances which:

LAST THREE CARGOES CARRIED ARE AS FOLLOWS:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil
2	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil
3	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil
4	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil
5	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil
6	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil	Crude Sunflower Seed Oil

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties

DATED: 17 OF JUNE, 2020.

FOR AND ON BEHALF OF

CISS GROUP Ukraine LLC

REGISTERED SUPERINTENDENT MEMBER OF FOSFA

