



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciss-group.com

CERTIFICATE No.: SGD00431/1

ORIGINAL

TANK CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

CRUDE SUNFLOWER SEED OIL IN BULK

Vessel:

M/T "KURA RIVER"

Quantity:

2 996, 272 MT

B/L No. & Date:

No 1 dd 16.06.2020

Shipper:

Trade House "Chernozemye" LLC, office 413, 3,
Peter the Great Sq., Lipetsk, 398001, Russia

Consignee:

TO ORDER
PAM YAG GIDA VE KIMYA SANAYI VE TICARET LTD STI (TAX
NUMBER 720 007 0609)

Notify address:

**SEKİLİ MAHALLESİ, E-90 KARAYOLU CADDE, NO :19/1 , NİZİP
GAZİANTEP 27700, TURKIYE**

Port of loading:

port Kavkaz, Russia

Port of discharge:

Mersin port, Turkey

Vessel Tanks Nos.:

1, 2, 3, 4, 5, 6

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry:

CRUDE SUNFLOWER SEED OIL IN BULK

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 17 OF JUNE, 2020
FOR AND ON BEHALF OF CISS GROUP Ukraine LLC
FIRST CLASS INDEPENDENT SURVEYOR
REGISTERED SUPERINTENDENT MEMBER OF FOSFA

