

Gafta



Page 1/1

CISS Group PTE. LTD.
10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciss-group.com

CERTIFICATE No.: SGD00511

ORIGINAL

TANK CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: RUSSIAN CRUDE SUNFLOWER SEED OIL IN BULK

Vessel: M/T "GARMONIA"

Quantity: 6 274,768 mt

B/L No. & Date: No 1 dd 21.11.2020

Shipper: "Trade House "Chernozemye" LLC, office 413, 3,

Peter the Great Sq., Lipetsk, 398001, Russia

Consignee: TO ORDER

Notify address: KUCUKBAY YAG VE DETERJAN SANAYI A.S.

ANKARA CADDESI, NO:102, 35030

BORNOVA-IZMIR-TURKIYE

Port of loading: Kavkaz, Russia

Port of discharge: T.C.D.D. ALSANCAK PORT / IZMIR OR ANY TURKISH PORT

Vessel Tanks Nos.: 1p/s, 2p/s, 3p/s, 4p/s, 5p/s, 6p/s

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry:

RUSSIAN CRUDE SUNFLOWER SEED OIL IN BULK

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 23 OF NOVEMBER, 2020 FOR AND ON BEHALF OF CISS GROUP Ukraine LLC FIRST CLASS INDEPENDENT SURVEYOR REGISTERED SUPERINTENDENT MEMBER OF FOSFA



