



Commodities International
Shipping and Survey



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

Page 1/1

CERTIFICATE No.: SGD00517

ORIGINAL

LAST THREE CARGO CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: **RUSSIAN CRUDE SUNFLOWER SEED OIL, IN BULK**
Vessel: **M/T " VOLGOTRANS-2702"**
Quantity: **6 002,527 mt**
B/L No. & Date: **No 1 dd 03.12.2020**
Shipper: **"Trade House "Chernozemye" LLC, office 413, 3, Peter the Great Sq., Lipetsk, 398001, Russia**
Consignee: **TO ORDER**
Notify address: **Pier Agro Gıda San. Ve Tic.A.Ş. Adana Yumurtalık Serbest Bölge Şb. Sarımazı Serbest Bölge Mah. Adana Yumurtalık Serbest Bölgesi Ceyhan – ADANA**
Port of loading: **Kavkaz, Russia**
Port of discharge: **TOROS PORT**
Vessel Tanks Nos.: **1,2,3,4,5,6**

RESULTS OF INSPECTION

As per Captain of said vessel information the previous cargoes carried in the tanks, lines and pump systems were some substances which:

LAST THREE CARGOES CARRIED ARE AS FOLLOWS:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1	Sunflower Seed Oil	Sunflower Seed Oil	RBD Palm OIL
2	Sunflower Seed Oil	Sunflower Seed Oil	RBD Palm OIL
3	Sunflower Seed Oil	Sunflower Seed Oil	RBD Palm OLEIN
4	Sunflower Seed Oil	Sunflower Seed Oil	RBD Palm OLEIN
5	Sunflower Seed Oil	Sunflower Seed Oil	RBD Palm OIL
6	Sunflower Seed Oil	Sunflower Seed Oil	RBD Palm Stearin

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties

DATED: 03 OF DECEMBER, 2020.

FOR AND ON BEHALF OF
CISS GROUP Ukraine LLC
REGISTERED SUPERINTENDENT MEMBER OF FOSFA

