

Gafta F

FOSFA INTERNATIONAL

Page 1/1

CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciss-group.com

CERTIFICATE No.: SGD00517

ORIGINAL

TANK CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

RUSSIAN CRUDE SUNFLOWER SEED OIL, IN BULK

Vessel:

M/T " VOLGOTRANS-2702"

Quantity:

6 002,527 mt

B/L No. & Date:

No 1 dd 03.12.2020

Shipper:

"Trade House "Chernozemye" LLC, office 413, 3, Peter the

Great Sq., Lipetsk, 398001, Russia

Consignee:

TO ORDER

Notify address:

Pier Agro Gıda San. Ve Tic.A.Ş. Adana Yumurtalık Serbest

Bölge Şb. Sarımazı Serbest Bölge Mah. Adana Yumurtalık

Serbest Bölgesi Ceyhan - ADANA

Port of loading: Port of discharge: Vessel Tanks Nos.: Kavkaz, Russia TOROS PORT

1,2,3,4,5,6

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry:

RUSSIAN CRUDE SUNFLOWER SEED OIL, IN BULK

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 03 OF DECEMBER, 2020 FOR AND ON BEHALF OF CISS GROUP Ukraine LLC FIRST CLASS INDEPENDENT SURVEYOR REGISTERED SUPERINTENDENT MEMBER OF FOSFA





