

Gafta!



Page 1/1

CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciss-group.com

CERTIFICATE No.: SGD00519

ORIGINAL

TANK CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from Messrs. EXOIL, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: CRUDE SUNFLOWERSEED OIL, IN BULK

Vessel: M/T "GARMONIA"

Quantity: 6 283,547 mt

B/L No. & Date: **No 1 dd 10.12.2020**

Shipper: "Trade House "Chernozemye" LLC, office 413, 3, Peter the

Great Sq., Lipetsk, 398001, Russia

Consignee: TO ORDER

Notify address: TİRYAKİ AGRO GIDA SAN. VE TİC. A.Ş.

BAŞPINAR (ORGANİZE) OSB MAH. 3.ORG.SAN.BÖL. 83313

NOLU CAD. NO:6 ŞEHİTKAMİL GAZİANTEP TURKEY

Port of loading: Kavkaz, Russia
Port of discharge: Mersin port, Turkey

Vessel Tanks Nos.: 1p/s, 2p/s, 3p/s, 4p/s, 5p/s, 6p/s

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: and were found empty, clean, free from harmful material and in this respect the ships tanks, pumps and pipes are suitable to receive and carry:

CRUDE SUNFLOWERSEED OIL IN BULK

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 10 OF DECEMBER, 2020 FOR AND ON BEHALF OF CISS GROUP Ukraine LLC FIRST CLASS INDEPENDENT SURVEYOR REGISTERED SUPERINTENDENT MEMBER OF FOSFA





