



**Commodities International  
Shipping and Survey**

Gafta

**FOSFA**  
INTERNATIONAL

Page 1/1

**CISS Group PTE. LTD.**

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

**CERTIFICATE No.: UA01014**

**ORIGINAL**

## **TANK INSPECTION CERTIFICATE**

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN ORIGIN CRUDE RAPESEED OIL  
M2  
Vessel: 1446,900 MT  
Quantity: NOS. 1 AND 2 DD. 13.08.2020  
B/L No. & Date: LLC BELAZ  
Shipper: 65490, UKRAINE, TEPLDAR, AV. ENERGETYKIV, 73. OF. 1  
ON BEHALF OF TRADE AGRI EUROPE LTD  
"IZMAILSKA TORGOVA COMPANIA" LLC  
UKRAINE, ODESSA REGION, IZMAIL, ST.OSIPENKA, 30  
ON BEHALF OF TRADE AGRI EUROPE LTD  
Consignee: ASTRA BIOPLANT LTD  
BULGARIA,23  
7060 SLIVO POLE  
BULGARIA  
Notify address: ASTRA BIOPLANT LTD  
BULGARIA,23  
7060 SLIVO POLE  
BULGARIA  
Port of loading: IZMAIL, UKRAINE  
Port of discharge: RUSE-BULMARKET, BULGARIA  
Vessel Tanks Nos.: 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13 AND 14

### **RESULTS OF INSPECTION**

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: Based on LIST OF ACCEPTABLE PREVIOUS CARGOES mentioned in COMMISSION REGULATION (EU) No 579/2014 of 28 May 2014, tanks of a.m. vessel are suitable for caring: Ukrainian Origin Crude Rapeseed Oil not edible for Human consumption.

The last three cargoes as declared by the vessel are as follows:

| Ships Tanks N°             | Last cargo                | Second Last Cargo         | Third Last Cargo  |
|----------------------------|---------------------------|---------------------------|-------------------|
| 1; 2; 3; 4; 5; 6; 7; 8; 9; | CRUDE SUNFLOWER SEEDS OIL | CRUDE SUNFLOWER SEEDS OIL | CRUDE SOYBEAN OIL |
| 10; 11; 12; 13; 14.        | CRUDE SUNFLOWER SEEDS OIL | CRUDE SUNFLOWER SEEDS OIL | CRUDE SOYBEAN OIL |

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

**DATED: 13 OF AUGUST, 2020**

**For and on behalf of CISS GROUP Ukraine LLC**

**Registered Superintendent and Surveyor Member of FOSFA**

