



**Commodities International
Shipping and Survey**



**FOSFA
INTERNATIONAL**

CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.

e-mail: inspection@ciiss-group.com

CERTIFICATE No.: UA01014

Page 1/1

ORIGINAL

TANK CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN ORIGIN CRUDE RAPESEED OIL
Vessel:	M2
Quantity:	1446,900 MT
B/L No. & Date:	NOS. 1 AND 2 DD. 13.08.2020
Shipper:	LLC BELAZ 65490, UKRAINE, TEPLDAR, AV. ENERGETYKIV, 73. OF. 1 ON BEHALF OF TRADE AGRI EUROPE LTD "IZMAILSKA TORGOVA COMPANIA" LLC UKRAINE, ODESSA REGION, IZMAIL, ST. OSIPENKA, 30 ON BEHALF OF TRADE AGRI EUROPE LTD
Consignee:	ASTRA BIOPLANT LTD BULGARIA, 23 7060 SLIVO POLE BULGARIA
Notify address:	ASTRA BIOPLANT LTD BULGARIA, 23 7060 SLIVO POLE BULGARIA
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	RUSE-BULMARKET, BULGARIA
Vessel Tanks Nos.:	1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13 AND 14

RESULTS OF INSPECTION

As a result of our visual examinations, visibly accessible parts of ship's tank/s № 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13 AND 14 of barge M2 were inspected and found to be dry and clean, swept and suitable to carry UKRAINIAN ORIGIN CRUDE RAPESEED OIL

Tanks were found in all respects ready for loading of cargo:

UKRAINIAN ORIGIN CRUDE RAPESEED OIL

Last cargoes as declared by the barge:

- CRUDE SUNFLOWER SEEDS OIL;
- CRUDE SUNFLOWER SEEDS OIL;
- CRUDE SOYBEAN OIL

Tanks were inspected on 12.08.2020 from 10:00 hrs. to 11:00 hrs.

The results of inspection are valid for the time and place of inspection only.

DATED: 13 of AUGUST, 2020

For and on behalf of CISS GROUP UKRAINE

Registered Superintendent and Surveyor Member of GAFTA

