



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.
e-mail: inspection@ciss-group.com

CERTIFICATE No.: UA01015

ORIGINAL

TANK INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:

UKRAINIAN ORIGIN CRUDE RAPSEED OIL

Vessel:

M1

Quantity:

1334,260 MT

B/L No. & Date:

NO. 1 DD. 18.08.2020

Shipper:

"IZMAILSKA TORGHOVA COMPANIA" LLC

UKRAINE, ODESSA REGION, IZMAIL, ST. OSIPENKA, 30
ON BEHALF OF TRADE AGRI EUROPE LTD

ASTRA BIOPLANT LTD

BULGARIA,23

7060 SLIVO POLE

BULGARIA

ASTRA BIOPLANT LTD

BULGARIA,23

7060 SLIVO POLE

BULGARIA

IZMAIL, UKRAINE

RUSE-BULMARKET, BULGARIA

Consignee:

Notify address:

Port of loading:

Port of discharge:

Vessel Tanks Nos.:

RESULTS OF INSPECTION

We hereby certify that prior to loading the ship's tanks, pumps and pipelines were visually inspected for cleanliness as far as possible and accessible: Based on LIST OF ACCEPTABLE PREVIOUS CARGOES mentioned in COMMISSION REGULATION (EU) No 579/2014 of 28 May 2014, tanks of a.m. vessel are suitable for carrying: Ukrainian Origin Crude Rapeseed Oil not edible for Human consumption.

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1, 2; 3; 4; 5; 6; 7; 8; 9	CRUDE SUNFLOWER SEEDS OIL	CRUDE SUNFLOWER SEEDS OIL	CRUDE SUNFLOWER SEEDS OIL
10; 11; 12; 13; 14	CRUDE SUNFLOWER SEEDS OIL	CRUDE SUNFLOWER SEEDS OIL	CRUDE SUNFLOWER SEEDS OIL

These findings are valid for the time and place of inspection only. The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

DATED: 18 OF AUGUST, 2020

For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA



P. Komar