



CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.  
e-mail: inspection@ciss-group.com

CERTIFICATE No.: UA01015

Page 1/1

ORIGINAL

## TANK CLEANLINESS INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

|                       |   |
|-----------------------|---|
| Description of goods: | UKRAINIAN ORIGIN CRUDE RAPESEED OIL   |
| Vessel:               | M1  |
| Quantity:             | 1334,260 MT   |
| B/L No. & Date:       | NO. 1 DD. 18.08.2020  |
| Shipper:              | "IZMAILSKA TORGובה COMPANY" LLC<br>UKRAINE, ODESSA REGION, IZMAIL, ST. OSIPENKA, 30<br>ON BEHALF OF TRADE AGRI EUROPE LTD |
| Consignee:            | ASTRA BIOPANT LTD<br>BULGARIA, 23<br>7060 SLIVO POLE<br>BULGARIA  |
| Notify address:       | ASTRA BIOPANT LTD<br>BULGARIA, 23<br>7060 SLIVO POLE<br>BULGARIA  |
| Port of loading:      | IZMAIL, UKRAINE   |
| Port of discharge:    | RUSE-BULMARKET, BULGARIA  |
| Vessel Tanks Nos.:    | 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13 AND 14  |

### RESULTS OF INSPECTION

As a result of our visual examinations, visibly accessible parts of ship's tank/s № 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13 AND 14 of barge M1 were inspected and found to be dry and clean, swept and suitable to carry UKRAINIAN ORIGIN CRUDE RAPESEED OIL

Tanks were found in all respects ready for loading of cargo:

### UKRAINIAN ORIGIN CRUDE RAPESEED OIL

Last cargoes as declared by the barge:

- CRUDE SUNFLOWER SEEDS OIL
- CRUDE SUNFLOWER SEEDS OIL
- CRUDE SUNFLOWER SEEDS OIL

Tanks were inspected on 17.08.2020 from 14:40 hrs. to 15:20 hrs.

The results of inspection are valid for the time and place of inspection only.

DATED: 18 of AUGUST, 2020

For and on behalf of CISS GROUP UKRAINE

Registered Superintendent and Surveyor Member of GAFTA



P. Konyuk