



Commodities International  
Shipping and Survey



FOSSA  
INTERNATIONAL

Page 1/1

CISS Group PTE. LTD.

10, Anson Road, #29-05 A, International Plaza, Singapore, 079903.  
e-mail: inspection@ciiss-group.com

CERTIFICATE No.: SGS00795/2

ORIGINAL

## HOLD CLEANLINESS CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: BARLEY IN BULK, UKRAINE ORIGIN, CROP 2022  
Vessel: M/S CARCO GRUP 10  
Quantity: 1539,700 MT  
BL Nos. & Date: 2 DD 02.10.2022  
Shipper: LLC "BOOMSTYLE", Ukraine, 54001, Mykolaiv  
ON BEHALF OF VITAL INCORPORATED, UAE, DUBAI, OFFICE  
321, EMARAT ATRIUM BUILDING, AL WASAL AREA  
ON BEHALF OF AGROTRADE SOLUTIONS INC, 71 RAIMOND Rd,  
WEST HARTFORD, CONNECTICUT 06107 USA  
Consignee: TO ORDER  
Notify Address: Ameropa Grains SA  
Constanta Municipality, Romania  
Constanta Port Precincts, Berth 54, floor 1,  
County of Constanta, post code 900900  
Registry of Commerce No.: J 13/933/1996  
VAT: RO 8204170  
Port of loading: RENI, UKRAINE  
Port of discharge: Constanta/Romania in transit

As a result of our visual examinations, visibly accessible parts of vessel's hold No. 1 was inspected and found to be dry and clean, swept and suitable to carry BARLEY IN BULK, UKRAINE ORIGIN, CROP 2022.

Hold was found in all respects ready for loading of cargo: **BARLEY IN BULK, UKRAINE ORIGIN, CROP 2022.**

Last cargoes as declared by the vessel: 1. SFS in bulk; 2. Barley in bulk; 3. No info; 4. No info.

Cleaning procedure as declared by ship's Master

CLEANING	LEVEL A	DRY	YES/NO
	LEVEL B	WITH WATER	YES/NO
	LEVEL C	WATER+DETERGENT	YES/NO
	LEVEL D	WATER+DETERGENT+DESINFECTANT	YES/NO

Hold No. 1 was inspected from 15:30 hrs to 16:00 hrs 29.09.2022

The results of inspection are valid for the time and place of inspection only.

Dated: 02 of OCTOBER, 2022

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of GAFSA

