







Page 1/1

member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district,

5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CISS GROUP UKRAINE LLC

Port of loading:

CERTIFICATE No.: SGD01130

ORIGINAL

HOLDS SEALING CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: BARLEY IN BULK, UKRAINE ORIGIN, CROP 2023

 Vessel:
 M/S MEDUSA

 Quantity:
 779,440 MT

 BL No. & Date:
 1 DD 17.09.2023

Shipper: LLC «DEPORTSMAIL AGROBIZ», Ukraine, 65000, Odesa ON

BEHALF OF VITAL INCORPORATED, UAE, DUBAI, OFFICE

321,EMARAT ATRIUM BUILDING, AL WASAL AREA ON BEHALF OF AGROTRADE SOLUTIONS INC, 16192 COASTAL HWY, LEWES,

COUNTY OF SUSSEX, DE 1995871

Consignee: TO ORDER

Notify Address: Ameropa Grains SA

Constanta Municipality, Romania Constanta Port Precincts, Berth 54, floor 1, County of Constanta, post code 900900 Registry of Commerce

No.: J 13/933/1996 VAT: RO 8204170 RENI, UKRAINE

Port of discharge: CONSTANTA, ROMANIA (IN TRANSIT)

We, CISS GROUP Ukraine LLC, hereby certify that we performed sealing of the cargo Hold No. 1 and manholes, upon completion of loading M/S MEDUSA. All holds and hatches have been closed and sealed. Date: 17.09.2023 sealing from: 20:35 hrs to: 21:05 hrs.

B B	Seal No.
Hold No.	Hatches
1	C73651004, C73651005

The results of inspection are valid for the time and place of inspection only.

Dated: 21st of SEPTEMBER, 2023
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of GAFTA





