



Commodities International  
Shipping and Survey



FOSFA  
INTERNATIONAL

CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

Page 1/2

CERTIFICATE No.: SGD01292

ORIGINAL

## LOAD COMPARTMENT INSPECTION CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN MILLING WHEAT, CROP 2023, IN BULK
Vessel:	M/V ENDEAVOUR
Quantity:	3210,140 MT
BL No. & Date:	1 DD 01.04.2024
Shipper:	GREEN LIGHT LIMITED LIABILITY COMPANY UKRAINE, 65049, ODESA REGION, ODESA CITY, FRANKA IVANA STREET, BUILDING 55, OFFICE 8 ON BEHALF OF CONUNG CORPORATION ON BEHALF OF AGROTRADE SOLUTIONS INC.
Consignee:	TO ORDER
Notify Address:	SAVVAS HADJIGIORKIS & SONS LTD, 5350 FRENAROS, CYPRUS
Port of loading:	RENI, UKRAINE
Port of discharge:	LARNACA, CYPRUS

We, CISS GROUP Ukraine LLC, herewith report on the Loading Compartments Inspection carried out for following cargo/shipment in accordance with the instructions received and relevant instructions and the stipulation of the GMP Transport code.

The cargo as described above has to be loaded in the following cargo compartments

Hold	Cargo	Quantity	Previously Loaded cargos			
			First last cargo	Second last cargo	Third last cargo	Fourth last cargo
1	Wheat in bulk	3300	FERTILIZER IN B/B, BULK	UREA IN BULK	CLAY IN BULK	CEMENT IN B/B

Cleaning procedure as declared by ship`s Master

CLEANING	LEVEL A	DRY	YES/NO
	LEVEL B	WITH WATER	YES/NO
	LEVEL C	WATER+DETERGENT	YES/NO
	LEVEL D	WATER+DETERGENT+DESINFECTANT	YES/NO







**Commodities International  
Shipping and Survey**



**CISS GROUP UKRAINE LLC**  
member of **CISS GROUP Pte.Ltd. (Singapore)**  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

**Page 2/2**

**CERTIFICATE No.: SGD01292**

**ORIGINAL**

Method of cleaning for each previous voyage

Previously Loaded cargos	Method of cleaning
First last cargo	Dry cleaning, washing with fresh water, mopping by ship's crew
Second last cargo	Dry cleaning, washing with fresh water, mopping by ship's crew
Third last cargo	Dry cleaning, washing with fresh water, mopping by ship's crew
Fourth last cargo	Dry cleaning, washing with fresh water, mopping by ship's crew

The LCI was carried out at (place)	Reni, Ukraine	Date	22.03.2024
Started	16:30	Finished	17:30

The results of inspection are valid for the time and place of inspection only.

**This certificate is electronically signed and stamped.**

**Dated: 04th of APRIL, 2024**

**For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of GAFTA**



This certificate is issued to any job or services carried out within the GENERAL TERMS AND CONDITION OF BUSINESS printed overleaf. This certificate is not intended to relieve the parties of any relevant sales contract from their contractual obligations. The Company's responsibility under this Certificate is limited to proven negligence and will in no case be more than ten times the amount of the fees.