member of CISS GROUP Pte.Ltd. (Singapore)

CISS GROUP UKRAINE LLC

inspection@ciss-group.com

5, Odessa Blv., Ovidiopol district,

Lymanka village, Odessa region, 65037







Page 1/1

CERTIFICATE No.: SGD00814

ORIGINAL

HOLD SEALING CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN SUNFLOWER SEED MEAL, IN BULK.

Vessel: M/V «LUCKY» Quantity: 5409,308 MT

BL No. & Date: NO. 1 DD 27.12.2022 Shipper: GNT TRADE DMCC

OFFICE 32A, GOLD TOWER, CLUSTER 1, JLT, DUBAI, UAE

Consignee: TO ORDER

Notify Address: VITERRA AGRICOLA ESPAÑA, S.A.U

PLAZA PABLO RUIZ PICASSO, 1

28020 MADRID ESPAÑA

Port of loading: ODESSA, UKRAINE Port of discharge: TARRAGONA, SPAIN

We, CISS GROUP Ukraine LLC, hereby certify that we performed sealing of the cargo Holds Nos. 1, 2 and 3 and manholes of M/V «LUCKY», upon completion of loading. All holds and hatches have been closed and sealed. Date: 27.12.2022 sealing from: 13:0 hrs to: 13:30 hrs

Hold No	Seal No		
	Hatches	Manholes	
		Fore	Aft
314 1	C53583021	D40170891	D40170892
2	C53583022	D40170893	D40170894
3	C53583023	D40170895	D40170896

The results of inspection are valid for the time and place of inspection only.

This certificate is electronically signed and stamped.

DATED: 27th of DECEMBER, 2022
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of GAFTA





