





Page

1/1

CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CERTIFICATE No.: SGD00878

ORIGINAL

LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods: UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL IN BULK

Vessel: M/T SELIN D
Quantity: 6000,000 MT

B/L No. & Date: NO. 1 AND 2 DD 02.01.2023

Shipper: GNT EUROPE SA

CHEMIN JEAN BAPTISTE VANDELLE 3A

1290 VERSOIX, SWITZERLAND

Consignee: TO ORDER

Notify address: PIER AGRO GIDA SAN. VE TIC.A.S.

ADANA YUMURTALIK SERBEST BOLGE SB.

SARIMAZI SERBEST BOLGE MAH.

ADANA YUMURTALIK SERBEST BOLGESI

CEYHAN - ADANA

Port of loading: ODESA, UKRAINE

Port of discharge: TOROS/CEYHAN /TURKEY

Vessel Tanks Nos.: 1P/S; 2P/S; 3P/S; 4P/S; 5P/S; 6P/S; SLOP C

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1P	CSFCO	CSFCO	CSFCO
1S	CSFCO	CSFCO	CSFCO
2P	CSFCO	CSFCO	CSFCO
2S	CSFCO	CSFCO	CSFCO
3P	CSFCO	CSFCO	CSFCO
3S	CSFCO	CSFCO	CSFCO
4P	CSFCO	CSFCO	CSFCO
4S	CSFCO	CSFCO	CSFCO
5P	CSFCO	CSFCO	CSFCO
5S	CSFCO	CSFCO	CSFCO
6P	CSFCO	CSFCO	CSFCO
6S	CSFCO	CSFCO	CSFCO
SLOP C	CSFCO	CSFCO	CSFCO
	The second secon	The state of the s	

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 2nd of JANUARY, 2023
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA





