



Commodities International  
Shipping and Survey



Page 1/1

CISS GROUP UKRAINE LLC  
member of CISS GROUP Pte.Ltd. (Singapore)  
5, Odessa Blv., Ovidiopol district,  
Lymanka village, Odessa region, 65037  
inspection@ciiss-group.com

CERTIFICATE No.: SGD00929

ORIGINAL

## LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we hereby confirm as follows:

Description of goods:	UKRAINIAN ORIGIN CRUDE SUNFLOWER SEED OIL IN BULK
Vessel:	MT MRC MINA
Quantity:	6599,360 MT
B/L No. & Date:	NO. A1-IZMAIL DD 06.03.2023
Shipper:	AVANTAGRO LTD SUITE 1, SECOND FLOOR, SOUND & VISION HOUSE, FRANCIS RACHEL STR., VICTORIA, MAHE, SEYCHELLES ON BEHALF OF VIVACITY MK LLC
Consignee:	TO ORDER
Notify address:	ABALIOGLU YAG SANAYI VE TICARET A.S. 10006/1 SOKAK NO:19 A.O.S.B. CIGLI, IZMIR – TURKEY
Port of loading:	IZMAIL, UKRAINE
Port of discharge:	ALIAGA, TURKEY
Vessel Tanks Nos.:	2P/S, 3P/3S, 4P/S, 5P/S, 6P/S, 7P/S

## RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
2P	ULSD 10 PPM	CSFSO	UAN
2S	ULSD 10 PPM	CSFSO	UAN
3P	ULSD 10 PPM	CSFSO	UAN
3S	ULSD 10 PPM	CSFSO	UAN
4P	ULSD 10 PPM	CSFSO	UAN
4S	ULSD 10 PPM	CSFSO	UAN
5P	ULSD 10 PPM	CSFSO	UAN
5S	ULSD 10 PPM	CSFSO	UAN
6P	ULSD 10 PPM	CSFSO	UAN
6S	ULSD 10 PPM	CSFSO	UAN
7P	ULSD 10 PPM	CSFSO	UAN
7S	ULSD 10 PPM	CSFSO	UAN

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

**This certificate is electronically signed and stamped.**

DATED: 6th of MARCH, 2023

For and on behalf of CISS GROUP Ukraine LLC  
Registered Superintendent and Surveyor Member of FOSFA

