





CISS GROUP UKRAINE LLC member of CISS GROUP Pte.Ltd. (Singapore) 5, Odessa Blv., Ovidiopol district, Lymanka village, Odessa region, 65037 inspection@ciss-group.com

CERTIFICATE No.: SGD00937

ORIGINAL

LAST THREE CARGOES CERTIFICATE

In pursuance of an order received from our principal, requesting us to carry out inspection we

hereby confirm as follows: Description of goods:

CRUDE SUNFLOWER SEED OIL, UKRAINIAN ORIGIN

Vessel: MT "AC-D" Quantity: 6600,000 MT

B/L No. & Date: NO. 1 DD 12.03.2023 Shipper: AVANTAGRO LTD

SUITE 1, SECOND FLOOR, SOUND & VISION HOUSE, FRANCIS RACHEL STR., VICTORIA, MAHE, SEYCHELLES

ON BEHALF OF VIVACITY MK LLC

Consignee: TO ORDER

Notify address: SAYINLAR GIDA MADDELERİ SANAYİ VE TİCARET A.Ş.

3. Organize Sanayi Bölgesi 83303 nolu cadde no:3

Şehitkamil - GAZİANTEP

Port of loading: IZMAIL, UKRAINE

Port of discharge: GUNEY WIMBA TERMINAL, ISKENDERUN, TURKIYE Vessel Tanks Nos.: 1C, 2P, 3P, 4P, 5P, 6P, 7P, 2S, 3S, 4S, 5S, 6S, 7S

RESULTS OF INSPECTION

The last three cargoes as declared by the vessel are as follows:

Ships Tanks N°	Last cargo	Second Last Cargo	Third Last Cargo
1C	CSFSO	ULSD 10 PPM	ULSD 10 PPM
2P	CSFSO	ULSD 10 PPM	ULSD 10 PPM
2S	CSFSO	ULSD 10 PPM	ULSD 10 PPM
3P	CSFSO	ULSD 10 PPM	ULSD 10 PPM
3S	CSFSO	ULSD 10 PPM	ULSD 10 PPM
4P	CSFSO	ULSD 10 PPM	ULSD 10 PPM
4S	CSFSO	ULSD 10 PPM	ULSD 10 PPM
5P	CSFSO	ULSD 10 PPM	ULSD 10 PPM
5S	CSFSO	ULSD 10 PPM	ULSD 10 PPM
6P	CSFSO	ULSD 10 PPM	ULSD 10 PPM
6S	CSFSO	ULSD 10 PPM	ULSD 10 PPM
7P.	CSFSO	ULSD 10 PPM	ULSD 10 PPM
7S	CSFSO	ULSD 10 PPM	ULSD 10 PPM

These findings are valid for the time and place of inspection only.

The certificate does not relieve the Vessel, Carrier and any other party from their contractual obligations and duties.

This certificate is electronically signed and stamped.

DATED: 12th of MARCH, 2023
For and on behalf of CISS GROUP Ukraine LLC
Registered Superintendent and Surveyor Member of FOSFA





